Cqc



THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.

7,105,954 B2

Certificate

Issued

September 12, 2006

APR 1 9 2007

Serial No.

10/614,854

ALIV I W 500)

Title Docket No.

SENSOR INTERFACE CABLE HYD 012 PA

of Correction

Commissioner for Patents Certificate of Correction Branch PO Box 1450 Alexandria VA 22313-1450

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, Certificate of Correction Branch, PO Box 1450, Alexandria, VA 22313 on April 12, 2007.

Attorney

Reg. No. 33,348

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKES UNDER 35 U.S.C. 254 AND 37 C.F.R. 1.322

In the matter of U. S. Patent No. 7,105,954 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

- Col. 2, line 23, "first sensor leads the second cable" should read --first sensor leads; the second cable--;
- Col. 4, line 13, "26, 28. When the output" should read --26, 28. (New paragraph) When the output--;
- Col. 4, line 36, "circuit board 90 is approximately 5:1 times" should read --circuit board 90 is approximately 5.1 times--;
- Col. 4, line 67, "comprises 18 AWG cable," should read --comprises 18 AWG cable (no bold)--;
- Col. 5, line 2, "comprises 22 AWG cable," should read --comprises 22 AWG cable (no bold)--.

Patent No. US 7,105,954 B2 Page 2

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,

michael a flow

STEVENS & SHOWALTER, L.L.P.

Michael D. Folkerts

Reg. No. 33,348
7019 Corporate Way

Dayton OH 45459-4238 Telephone: 937/438-6848 Facsimile: 937/438-2124

Email:mfolkerts@sspatlaw.com

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,105,954 B2

DATED

: September 12, 2006

INVENTOR(S): Rand Kalani Ray

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 23, "first sensor leads the second cable" should read --first sensor leads; the second cable--;

Col. 4, line 13, "26, 28. When the output" should read --26, 28. (New paragraph) When the output--;

Col. 4, line 36, "circuit board 90 is approximately 5:1 times" should read --circuit board 90 is approximately 5.1 times--;

Col. 4, line 67, "comprises 18 AWG cable, " should read --comprises 18 AWG cable (no bold)--;

Col. 5, line 2, "comprises 22 AWG cable, " should read --comprises 22 AWG cable (no bold)--.

6... 1 9 2000

MAILING ADDRESS OF SENDER: Michael D. Folkerts Stevens & Showalter LLP 7019 Corporate Way

Dayton OH 45459-4238

PATENT NO.

7,105,954 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

